#### \*\*\* MATERIAL SAFETY DATA SHEET \*\*\*

#### Date of preparation: 07/25/05

# Page 1 4702024

Manufacturer	: W. R. MEADOWS, INC.			- H M I S -				
Address	: 2300 West Valley Boulevard : Pomona, CA 91768			Health :1   Flammability :1				
					Reactivity :0			
Telephone #	: (909) 469-				Pe	rsonal Protection	:	
Emergency #	: 1-800-424	-9300 Chemt	rec			( A. Olivik ( O. Madara		* 01
Mfg. code I.D.	: 4702021			(Hazard Ra	ating: 0=Leas	t,1=Slight,2=Modera	ite,3=High,4=Extre	eme,^=Chronic)
Trade Name		EAL GG SET		GENT - BLACK				
SECTION II-A		HAZA	RDOL	JS COMPC	NENTS			
				% by	SARA	VAPOR PRESSURE	LEL	
No. Component		CA	\S#	Weight	313	(mm Hg @ 20 C)	(@ 25 C)	
1. Diethylene Glyco	l Dibenzoate	-	-55-8	10-15	NO	N/A	N/A	
2. Dipropylene Glyc			8-31-4	10-15	NO	N/A	N/A	
3. Limestone	0. 2.00200.00	-	-65-3	50-55	NO	N/A	N/A	
4. Bisphenol A/Epic	chlorohvdrin Resi		8-38-6	5-10	NO	N/A	N/A	
5. Silicon Dioxide, A	,		2-90-7	1-5	NO	N/A	N/A	
<ol> <li>Dimethylbenzyl H</li> </ol>			15-9	5-10	YES	2.00	N/A	
, ,	ents of this prod					N/A = Not Applicable		
None of the compon		401 410 10000	ji lizeu as	s carcinogenic.		N/A = NOLAPPIICADE	7	
					und Amendme	A = Not Applicable and Reauthorization		RA) and 40 CFR I
Under the reporting	requirements of	Section 313	of Title II	I of the Superfu		nts and Reauthorizati		RA) and 40 CFR I
Under the reporting	requirements of d on the 313 List	Section 313 (40 CFR Par	of Title II t 373.65)	I of the Superfu	nder the headir	nts and Reauthorizating "SARA 313".		RA) and 40 CFR I
Under the reporting 372, chemicals listed	requirements of d on the 313 List	Section 313 (40 CFR Par	of Title II t 373.65)	I of the Superfu are identified u	nder the headir	nts and Reauthorizating "SARA 313".		RA) and 40 CFR I
Under the reporting 372, chemicals listed	requirements of d on the 313 List B OSHA	Section 313 (40 CFR Par OCCU	of Title II t 373.65)	I of the Superfu are identified u	nder the headir	nts and Reauthorizati ng "SARA 313". <b>_IMITS</b> ACGIH		RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-B No. PEL/TWA 1. N/E	OSHA PEL/CEILING N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E	of Title II t 373.65) PATIO SKIN N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E	NTLV/CEILING	nts and Reauthorizati ng "SARA 313". LIMITS ACGIH 5 TLV/STEL N/E	SKIN N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-B No. PEL/TWA 1. N/E 2. N/E	OSHA PEL/CEILING N/E N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E	of Title II t 373.65) <b>PATIO</b> SKIN N/E N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E N/E	NOSURE L TLV/CEILING N/E N/E	nts and Reauthorizati ng "SARA 313". LIMITS ACGIH 5 TLV/STEL N/E N/E N/E	SKIN N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m <sup>3</sup>	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup>	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E	of Title II t 373.65) PATIO SKIN N/E N/E N/E N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E N/E 10 mg/m*	NOSURE L TLV/CEILING N/E N/E N/E N/E	nts and Reauthorizati ng "SARA 313". LIMITS ACGIH 5 TLV/STEL N/E N/E N/E N/E	SKIN N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³* 4. N/E	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup> N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E	of Title II t 373.65) PATIO SKIN N/E N/E N/E N/E N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E N/E 10 mg/m <sup>*</sup> N/E	TLV/CEILING N/E N/E N/E N/E N/E N/E	nts and Reauthorizati ng "SARA 313". <b>LIMITS</b> ACGIH 5 TLV/STEL N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³* 4. N/E 5. 80 mg/m³	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup> N/E N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E N/E	of Title II t 373.65) PATIO SKIN N/E N/E N/E N/E N/E N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E 10 mg/m <sup>3*</sup> N/E 5 mg/m <sup>3**</sup>	TLV/CEILING N/E N/E N/E N/E N/E 10 mg/m*	nts and Reauthorizati ng "SARA 313". <b>LIMITS</b> ACGIH 5 TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting         372, chemicals listed         SECTION II-B         No.       PEL/TWA         1.       N/E         2.       N/E         3.       15 mg/m³*         4.       N/E	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup> N/E N/E N/E N/E N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E	of Title II t 373.65) PATIO SKIN N/E N/E N/E N/E N/E N/E N/E N/E	I of the Superfu are identified un ONAL EXP TLV/TWA N/E N/E 10 mg/m <sup>*</sup> N/E	TLV/CEILING N/E N/E N/E N/E N/E N/E	nts and Reauthorizati ng "SARA 313". <b>LIMITS</b> ACGIH 5 TLV/STEL N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³* 4. N/E 5. 80 mg/m³ 6. N/E	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup> N/E N/E N/E N/E N/E	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E N/E N/E	of Title II t 373.65) PATIO N/E N/E N/E N/E N/E N/E N/E *** = Res	I of the Superfu are identified un <b>DNAL EXP</b> TLV/TWA N/E 10 mg/m <sup>**</sup> N/E 5 mg/m <sup>**</sup> N/E pirable dust	TLV/CEILING N/E N/E N/E N/E N/E 10 mg/m*	nts and Reauthorizati ng "SARA 313". <b>LIMITS</b> ACGIH 5 TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³* 4. N/E 5. 80 mg/m³ 6. N/E N/E = Not established SECTION III	OSHA PEL/CEILING N/E 5 mg/m <sup>3</sup> N/E N/E N/E N/E N/E d * = Tota	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E N/E N/E al dust	of Title II t 373.65) PATIO N/E N/E N/E N/E N/E N/E N/E *** = Res	I of the Superfu are identified un ONAL EXP TLV/TWA N/E 10 mg/m* N/E 5 mg/m** N/E pirable dust DATA	TLV/CEILING N/E N/E N/E N/E N/E 10 mg/m*	nts and Reauthorizati ng "SARA 313". <b>LIMITS</b> ACGIH 5 TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³ 4. N/E 5. 80 mg/m³ 6. N/E N/E = Not established SECTION III Boiling Point Evaporation Rate	requirements of d on the 313 List OSHA PEL/CEILING N/E N/E 5 mg/m <sup>3</sup> N/E N/E N/E d * = Tota : 250 d : < 1 (e	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E al dust PHYS egrees F ether = 1)	of Title II t 373.65) PATIO N/E N/E N/E N/E N/E N/E N/E *** = Res	I of the Superfu are identified un ONAL EXP TLV/TWA N/E 10 mg/m* N/E 5 mg/m** N/E pirable dust DATA % Volatile % Volatile	N/E N/E N/E N/E N/E N/E 10 mg/m <sup>*</sup> N/E	nts and Reauthorizati ng "SARA 313". <b>JIMITS</b> ACGIH TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR I
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³* 4. N/E 5. 80 mg/m³ 6. N/E N/E = Not established SECTION III Boiling Point Evaporation Rate Vapor Density	requirements of d on the 313 List OSHA PEL/CEILING N/E N/E 5 mg/m <sup>3</sup> N/E N/E d * = Tot: : 250 d : < 1 (e : > 1 (a	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E al dust PHYS egrees F ether = 1) hir = 1)	of Title II t 373.65) PATIO N/E N/E N/E N/E N/E N/E N/E *** = Res	I of the Superfu are identified un ONAL EXP TLV/TWA N/E 10 mg/m* N/E 5 mg/m** N/E pirable dust DATA % Volatile	N/E N/E N/E N/E N/E N/E 10 mg/m <sup>*</sup> N/E	nts and Reauthorizati ng "SARA 313". <b>JIMITS</b> ACGIH 3 TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR
Under the reporting 372, chemicals listed SECTION II-E No. PEL/TWA 1. N/E 2. N/E 3. 15 mg/m³ 4. N/E 5. 80 mg/m³ 6. N/E N/E = Not established SECTION III Boiling Point Evaporation Rate	requirements of d on the 313 List OSHA PEL/CEILING N/E N/E 5 mg/m <sup>3</sup> N/E N/E d * = Tot: : 250 d : < 1 (e : > 1 (a	Section 313 (40 CFR Par OCCU PEL/STEL N/E N/E N/E N/E N/E al dust PHYS egrees F ether = 1)	of Title II t 373.65) PATIO N/E N/E N/E N/E N/E N/E N/E *** = Res	I of the Superfu are identified un ONAL EXP TLV/TWA N/E 10 mg/m* N/E 5 mg/m** N/E pirable dust DATA % Volatile % Volatile	N/E N/E N/E N/E N/E N/E 10 mg/m <sup>*</sup> N/E	nts and Reauthorizati ng "SARA 313". <b>JIMITS</b> ACGIH TLV/STEL N/E N/E N/E N/E N/E N/E N/E N/E	SKIN N/E N/E N/E N/E N/E N/E N/E N/E	RA) and 40 CFR

SKIN CONTACT: Based on the presence of component 4 contact with the skin may result in skin sensitization to epoxies. Individuals who have developed a skin sensitization can develop these symptoms as a result of contact with very small amounts of liquid material or as a result of exposure to vapor. This skin sensitization may be temporary or permanent. Once an individual is diagnosed as being sensitized, no further exposure can be permitted.

**INHALATION:** Based on the presence of component 5 exposure to mist or spray may cause coughing, sneezing, or other symptoms of upper respiratory tract irritation. Based on the presence of component 4 as a result of repeated overexposures or exposure to a single large dose, certain individuals may develop lung sensitization (chemical asthma) to epoxies which will cause them to react to a later exposure at very low levels. Once an individual is diagnosed as being sensitized, no further exposure can be permitted. This lung sensitization may be either temporary or permanent. **INGESTION:** This product may cause mild to moderate irritation of the gastrointestinal tract.

**SIGNS AND SYMPTOMS:** Symptoms of eye irritation include pain, tearing, reddening, and swelling. Symptoms of skin irritation include reddening, swelling, rash, and redness. Symptoms of respiratory irritation include runny nose, sore throat, coughing, chest discomfort, shortness of breath, and reduced lung function. Symptoms of gastrointestinal irritation include sore throat, abdominal pain, nausea, vomiting, and diarrhea. Skin sensitization results in allergic dermatitis which may include rash, itching, hives and swelling of extremities. Lung sensitization results in asthma-like symptoms: chest tightness, shortness of breath, wheezing and coughing. These symptoms may be immediate or delayed up to several hours.

## \*\*\* MATERIAL SAFETY DATA SHEET \*\*\*

## Date of preparation: 07/25/05

AGGRAVATED MEDICAL CONDITIONS: Pre-existing skin, eye, and respiratory disorders may be aggravated by exposure to this product. Persons with asthmatic-type conditions, chronic bronchitis, other chronic respiratory diseases, recurrent skin eczema, sensitization or allergies should be excluded from working with epoxies.

OTHER HEALTH EFFECTS: None recognized.

#### **SECTION V**

## **EMERGENCY AND FIRST AID PROCEDURES**

**EYE CONTACT:** If irritation or redness develops, move victim away from exposure source and into fresh air. Flush eyes with water for fifteen (15) minutes. If symptoms persist, seek medical attention.

SKIN CONTACT: Remove contaminated shoes and clothing. Cleanse affected area(s) thoroughly by washing with mild soap and water. If irritation or redness develops and persists, seek medical attention.

**INHALATION:** If respiratory symptoms develop, move victim away from exposure source and into fresh air. If symptoms persist, seek medical attention. If victim is not breathing, immediately begin artificial respiration. If breathing difficulties develop, oxygen should be administered by qualified personnel. Seek immediate medical attention.

**INGESTION:** Do not induce vomiting. If vomiting spontaneously occurs, keep the victim's head below the hips to prevent aspiration into the lungs. Since aspiration into the lungs can cause very serious, permanent damage, the decision of whether to induce vomiting or not should be made by a physician. Damage from lung aspiration must be weighed against toxicity when considering emptying the stomach. Consult a physician, hospital, or poison control center and/or transport to an emergency facility immediately.

#### SECTION VI FIRE AND EXPLOSION HAZARDS

FLAMMABILITY CLASSIFICATION

NFPA: Not regulatedDOT: Not regulated

FLASH POINT: Greater than 210 degrees F

EXTINGUISHING MEDIA: Use water fog, foam, dry chemical, or Carbon Dioxide.

**SPECIAL FIRE FIGHTING PROCEDURES AND PRECAUTIONS:** Clear area of unprotected personnel. Do not enter confined fire space without helmet, face shield, bunker coat, gloves, rubber boots, and a positive pressure NIOSH approved self-contained breathing apparatus.

**UNUSUAL FIRE AND EXPLOSION HAZARDS:** Containers exposed to intense heat from fires should be cooled with water to prevent vapor pressure buildup which may result in container rupture. Container areas exposed to direct flame contact should be cooled with large quantities of water as needed to prevent weakening of container structure.

#### SECTION VII REACTIVITY

STABILITY: Stable

HAZARDOUS POLYMERIZATION: Will not occur

**CONDITIONS AND MATERIALS TO AVOID:** Avoid oxidizing materials, strong acids, lead, copper, and their alloys, zinc, amines, polyamines, and polyamides under uncontrolled conditions

HAZARDOUS DECOMPOSITION PRODUCTS: Combustion may yield Carbon Dioxide, Carbon Monoxide, and/or incomplete combustion products. Do not breathe smoke or fumes. Wear appropriate protective equipment.

## SECTION VIII EMPLOYEE PROTECTION

**RESPIRATORY PROTECTION:** Use ventilation as required to control vapor concentrations - at least 10 air changes per hour are recommended for good general room ventilation. If exposure exceeds the PEL/TLV, use the appropriate NIOSH approved respirator.

**PROTECTIVE CLOTHING:** Wear safety glasses, goggles, or a splash shield to prevent eye contact. Contact lenses should not be worn. Wear appropriate gloves and protective clothing to prevent contact with skin and clothing.

ADDITIONAL PROTECTIVE MEASURES: Eye wash fountains and safety showers should be available for use in an emergency.

## SECTION IX ENVIRONMENTAL PROTECTION

SPILL OR LEAK PROCEDURES: LARGE SPILLS>> Evacuate the hazard area of unprotected personnel. Wear appropriate respirator and protective clothing. Shut off source of leak only if safe to do so. Dike and contain. If vapor cloud forms, water fog may be used to suppress; contain run-off. Remove with vacuum trucks or pump to storage/salvage vessels. Soak up residue with an absorbent such as clay, sand, or other suitable material; place in non-leaking containers for proper disposal. Flush area with water to remove trace residue; dispose of flush solutions as above. SMALL SPILLS>> Take up with an absorbent material and place in non-leaking containers; seal tightly for proper disposal. WASTE DISPOSAL: Observe all Federal, State and local regulations regarding proper disposal.

SECTION X

#### ADDITIONAL PRECAUTIONS

Containers can contain hazardous product residues even when empty. Wash with soap and water before eating, drinking, smoking or using toilet facilities.

The information contained herein is based on the data available to us and is believed to be correct. However, we make no warranty, expressed or implied regarding the accuracy of this data or the results to be obtained from the use thereof. We assume no responsibility for injury from the use of the product described herein.

4702024 Page 2